	- ** <u></u>	SECRET	REPORT		
					25X1
OUNTRY	Czechoslovakia		DATE DIST	R. 31 Aug.	53
JBJECT	Electronic Equ	ilpment of the Air Ford	NO. OF PA	AGES 2	
.ACE CQUIRED	· ·		NO. OF EN		
ATE			SUPPLEME	NT TO	25X1
CQUIRED			REPOR		 25X1
ATE OF IN				m	
	TH	IIS IS UNEVALUATED INFORM	MATION		25X1
₩10-16	. Wugwin and Val	ta communications e	quinment were use	d in	
Fug-16	, Fug-10 and Yal	ta communications e	quipment were use behind by the Ger	d in mans and	
back t the CS inform	o the MIG bases. R is still in it ation is relayed ganization. In	the the searly stages and to Moscow by the San emergency these	information was e early warning subject officers at officers would also	relayed ystem in rning tached to	2
back to the CS inform the or certain	o the MIG bases. R is still in it ation is relayed ganization. In nly assume compl	the the the searly stages and to Moscow by the Sear an emergency these ete control of the Mannheim radar were	information was e early warning so the early warning so the early warning so the early was oviet officers would also system.	relayed ystem in rning tached to	
back to the CS informathe or certain	o the MIG bases. R is still in it ation is relayed ganization. In any assume compleround Freya and Soviet origin at 12, E 17-317, an	the the the searly stages and to Moscow by the San emergency these ete control of the Mannheim radar were the airfields at Bad near Budisov /N 4	information was e early warning s the early war oviet officers at officers would alsystem. used. radar rno, Gottwaldov-0 9-16, E 16-007.	relayed ystem in rning tached to most	
back to the CS inform the or certain only a of the Fr	o the MIG bases. R is still in it ation is relayed ganization. In any assume compleround Freya and Soviet origin at 12, E 17-317, an eya and Mannheim a radar o	the the the searly stages and to Moscow by the Sear emergency these ete control of the Mannheim radar were the airfields at Be	information was e early warning s the early warout officers at officers would also system. used. radar rno. Gottwaldov-0 9-16, E 16-00/.	relayed ystem in rning tached to most	25

SECRET

SECURITY INFORMATION

SECRET

- 2 -

25X1

5. There was a great deal of variation in the quality of the electronics equipment supplied by the USSR, even when it had the same trade name. The transmitters were the chief source of trouble.

25X1

- 6. Crystals and tubes for VHF equipment were in very short supply. Spare parts for the Fug-10 and Fug-16 were manufactured by Tesla and there was usually an adequate supply of these on hand. In general, however, tubes had to be used sparingly.
- 7. Tubes were available for some radios of Czechoslovak make and could be obtained from stores by bribing the sales personnel. Tubes for foreign made radios were practically unobtainable.

25X1

complaining of having to wait several months for tubes for even some Czechoslovak radios. The spare tubes came from the Tesla factory at Prague-Vysocany.

- 8. The inadequacy of electronic equipment was a definite safety hazard especially in bad weather. To conserve the VHF equipment, the use of VHF within Czechoslovakia was prohibited except during sunrise and sunset when reception on command and liaison sets was very poor. Aircraft flying to the other Satellites used only liaison and command sets.
- 9. Whenever the VHF equipment became inoperative on a flight going from Czechoslovakia to Scandinavia, and the aircraft was still over Czechoslovakia, the pilot had to return to Prague-Ruzyne /N 50-05, E 14-16/ where either the deficiency was corrected or he changed aircraft. If already outside of Czechoslovakia when the VHF went out, the radio operator switched to W/T.
- 10. Each CSA captain said his own private prayers in hopes of getting a plane with a good VHF in the event of bad weather because the command liaison reception was very poor.

SECRET